


Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

Inspections included in this report

Actual Date	01/07/2024 11:13:00	 01/07/2024
Inspection Status	Completed	
Inspection Type	Playground-Annual	
Inspector	Louisa Hill	
Provider	Mendip	
Site Name	Tannery Field (Glanvil Road), Street	

Finding Summary

Tannery Field (Glanvil Road), Street Findings

Asset	Finding Title	Creation Date	Risk Level
Site - General Surface - Grass	Surface - Encroaching vegetation/trees	01/07/2024 11:13:00	Low
Fence - Timber Post & Rail	Item - Loose in Ground	01/07/2024 11:13:00	Very Low
Fence - Timber Post & Rail	Fixtures - Loose or Missing	01/07/2024 11:13:00	Very Low

Inspection - Tannery Field (Glanvil Road), Street - 01/07/2024 11:13:00

Actual Date	01/07/2024 11:13:00
Inspection Status	Completed
Inspection Type	Playground-Annual
Inspector	Louisa Hill
Provider	Mendip
Site Name	Tannery Field (Glanvil Road), Street

Address	ASTS50POS0008
Notes	
Postcode	BA16 0TA
Site Name	Tannery Field (Glanvil Road), Street

Tannery Field (Glanvil Road), Street Inspected Asset List (see Inspection Notes for exceptions)

Asset Category	Perimeter
Asset Name	Entrance - Maintenance Gate
Asset Sub Type	Maintenance Gate
Asset Type	Entrance
Manufacturer	

Asset Category	Perimeter
Asset Name	Entrance - Self Closing Gate x2
Asset Sub Type	Self Closing Gate
Asset Type	Entrance
Manufacturer	

Asset Category	Perimeter
Asset Name	Fence - Hedgerow
Asset Sub Type	Hedge
Asset Type	Fencing
Manufacturer	

Asset Category	Perimeter
Asset Name	Fence - Timber Post & Rail
Asset Sub Type	Post & Rail
Asset Type	Fencing
Manufacturer	

Asset Category	Surface
Asset Name	Site - General Surface - Grass
Asset Sub Type	Grass
Asset Type	General Surface
Manufacturer	

Asset Category	Site
Asset Name	The Overall Site
Asset Sub Type	The Overall Site
Asset Type	Site
Manufacturer	

Findings reported within the Inspection

Fence - Timber Post & Rail - Findings

Asset	Fence - Timber Post & Rail
Cause	Wear and Tear
Finding Creation Date	01/07/2024 11:13:00
Finding Group	Maintenance
Finding ID	F15408
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Item - Loose in Ground
Location	
Risk Level	Very Low

Finding Photos



Asset	Fence - Timber Post & Rail
Cause	Wear and Tear
Finding Creation Date	01/07/2024 11:13:00
Finding Group	Maintenance
Finding ID	F15407
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Site - General Surface - Grass - Finding

Asset	Site - General Surface - Grass
Cause	Routine
Finding Creation Date	01/07/2024 11:13:00
Finding Group	Maintenance
Finding ID	F15406
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Surface - Encroaching vegetation/trees
Location	
Risk Level	Low

Finding Photos

