


Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

Inspections included in this report

Actual Date	01/07/2024 08:41:00	 01/07/2024
Inspection Status	Completed	
Inspection Type	Playground-Annual	
Inspector	Louisa Hill	
Provider	Mendip	
Site Name	Mendip View, Street	


Finding Summary

Mendip View, Street Findings

Asset	Finding Title	Creation Date	Risk Level
Entrance - Self Closing Gate	Timber - Splintered	01/07/2024 08:41:00	Low
Play - Toddler Multi Play - Wet Pour Surface	Surface - Perimeter of Surface Shrunk from Edgings	01/07/2024 08:41:00	Low
Play - Toddler Multi Play	Item - Requires cleaning	01/07/2024 08:41:00	Very Low
Play - Toddler Multi Play - Wet Pour Surface	Surface - Small Holes	01/07/2024 08:41:00	Very Low
Play - Toddler Multi Play - Wet Pour Surface	Surface - Weeds	01/07/2024 08:41:00	Very Low
Swing 1 Bay 1 Cradle Seat	Item - Rusting in places	01/07/2024 08:41:00	Very Low
Swing 1 Bay 1 Cradle Seat Surface	Surface - Edges Shrunk	01/07/2024 08:41:00	Very Low



Inspection - Mendip View, Street - 01/07/2024 08:41:00

Actual Date	01/07/2024 08:41:00	 01/07/2024
Inspection Status	Completed	
Inspection Type	Playground-Annual	
Inspector	Louisa Hill	
Provider	Mendip	
Site Name	Mendip View, Street	

Address	ASTN50PPOS0001PL0002
Notes	
Postcode	BA16 9SJ
Site Name	Mendip View, Street

Mendip View, Street Inspected Asset List (see Inspection Notes for exceptions)

Asset Category	Perimeter
Asset Name	Entrance - Self Closing Gate
Asset Sub Type	Self Closing Gate
Asset Type	Entrance
Manufacturer	

Asset Category	Perimeter
Asset Name	Fence - Timber Pailing
Asset Sub Type	Timber Pailing
Asset Type	Fencing
Manufacturer	

Asset Category	Equipment (Outdoor Play)
Asset Name	Play - Low Rotator
Asset Sub Type	Other (Specify in Name Field)
Asset Type	Agility
Manufacturer	

Asset Category	Surface
Asset Name	Play - Low Rotator - Wet Pour Surface
Asset Sub Type	Wet Pour
Asset Type	Safer Surface
Manufacturer	

Asset Category	Equipment (Outdoor Play)
Asset Name	Play - Toddler Multi Play
Asset Sub Type	Multiplay Unit - Toddler
Asset Type	Multiplay
Manufacturer	Wicksteed Leisure Ltd

Asset Category	Surface
Asset Name	Play - Toddler Multi Play - Wet Pour Surface
Asset Sub Type	Wet Pour
Asset Type	Safer Surface
Manufacturer	

Asset Category	Site
Asset Name	Signage
Asset Sub Type	Signage
Asset Type	Signage
Manufacturer	

Asset Category	Facilities
Asset Name	Site - Facility - Bench Seat
Asset Sub Type	Bench with back rest
Asset Type	Seating
Manufacturer	

Asset Category	Facilities
Asset Name	Site - Facility - Litter Bin
Asset Sub Type	Litter Bin
Asset Type	Bins
Manufacturer	

Asset Category	Surface
Asset Name	Site - General Surface - Grass
Asset Sub Type	Grass
Asset Type	General Surface
Manufacturer	

Asset Category	Equipment (Outdoor Play)
Asset Name	Swing 1 Bay 1 Cradle Seat
Asset Sub Type	Type 1 - Traditional (Toddler Seats)
Asset Type	Swing
Manufacturer	

Asset Category	Surface
Asset Name	Swing 1 Bay 1 Cradle Seat Surface
Asset Sub Type	Wet Pour
Asset Type	Safer Surface
Manufacturer	

Asset Category	Site
Asset Name	The Overall Site
Asset Sub Type	The Overall Site
Asset Type	Site
Manufacturer	

Findings reported within the Inspection

Entrance - Self Closing Gate - Finding

Asset	Entrance - Self Closing Gate
Cause	Wear and Tear
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15328
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Timber - Splintered
Location	
Risk Level	Low

Finding Photos



Play - Toddler Multi Play - Finding

Asset	Play - Toddler Multi Play
Cause	Wear and Tear
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15332
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Item - Requires cleaning
Location	
Risk Level	Very Low

Finding Photos



Play - Toddler Multi Play - Wet Pour Surface - Findings

Asset	Play - Toddler Multi Play - Wet Pour Surface
Cause	Wear and Tear
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15331
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Surface - Small Holes
Location	
Risk Level	Very Low

Finding Photos



Asset	Play - Toddler Multi Play - Wet Pour Surface
Cause	Routine
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15330
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Surface - Weeds
Location	
Risk Level	Very Low

Finding Photos



Asset	Play - Toddler Multi Play - Wet Pour Surface
Cause	Wear and Tear
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15329
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Surface - Perimeter of Surface Shrunk from Edgings
Location	
Risk Level	Low

Finding Photos



Swing 1 Bay 1 Cradle Seat - Finding

Asset	Swing 1 Bay 1 Cradle Seat
Cause	Wear and Tear
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15334
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Item - Rusting in places
Location	
Risk Level	Very Low

Finding Photos



Swing 1 Bay 1 Cradle Seat Surface - Finding

Asset	Swing 1 Bay 1 Cradle Seat Surface
Cause	Wear and Tear
Finding Creation Date	01/07/2024 08:41:00
Finding Group	Maintenance
Finding ID	F15333
Finding Notes	
Finding Resolved Date	09/09/2024 00:00:00
Finding Status	Closed
Finding Title	Surface - Edges Shrunk
Location	
Risk Level	Very Low

Finding Photos

