




# Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

## Inspections included in this report

Actual Date	01/07/2024 10:13:00	 01/07/2024
Inspection Status	Completed	
Inspection Type	Playground-Annual	
Inspector	Louisa Hill	
Provider	Mendip	
Site Name	Ringolds Way, Street	

# Finding Summary

## Ringolds Way, Street Findings

Asset	Finding Title	Creation Date	Risk Level
Track ride tower	Item - Rope Attached	01/07/2024 10:13:00	Medium
3 picnic tables	Timber - Splintered	01/07/2024 10:13:00	Low
Entrance - Self Closing Gate (MH) x2	Gate - Violent Action	01/07/2024 10:13:00	Low
Entrance - Self Closing Gate (MH) x2	Item - Repair/s - Minor	01/07/2024 10:13:00	Low
Quad tower with climbing net and net bridge multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Low
Seat x2	Item - Broken	01/07/2024 10:13:00	Low
Supernova carousel	Item - Parts Missing	01/07/2024 10:13:00	Low
1 bay 2 cradle swings	Surface - Wearing	01/07/2024 10:13:00	Very Low
2 bay swing and birds nest swing	Item - Cap(s) missing	01/07/2024 10:13:00	Very Low
3 picnic tables	Item - Graffiti - Present	01/07/2024 10:13:00	Very Low
3 picnic tables	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Fence - Timber Paling	Timber - Smashed	01/07/2024 10:13:00	Very Low
Quad tower with climbing net and net bridge multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Quad tower with climbing net and net bridge multi unit	Item - Graffiti - Present	01/07/2024 10:13:00	Very Low
Quad tower with climbing net and net bridge multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Quad tower with climbing net and net bridge multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Quad tower with climbing net and net bridge multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Quad tower with climbing net and net bridge multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
The Overall Site	Site needs spraying for weeds	01/07/2024 10:13:00	Very Low
Toddler tower multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Toddler tower multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Toddler tower multi unit	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Toddler tower multi unit	Surface - Wearing	01/07/2024 10:13:00	Very Low
Track ride tower	Item - Parts Missing	01/07/2024 10:13:00	Very Low
Track ride tower	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low
Track ride tower	Fixtures - Loose or Missing	01/07/2024 10:13:00	Very Low



## Inspection - Ringolds Way, Street - 01/07/2024 10:13:00

Actual Date	01/07/2024 10:13:00
Inspection Status	Completed
Inspection Type	Playground-Annual
Inspector	Louisa Hill
Provider	Mendip
Site Name	Ringolds Way, Street

  
01/07/2024

Address	ASTW50POS0002PL0001
Notes	
Postcode	BA16 0RF
Site Name	Ringolds Way, Street

### Ringolds Way, Street Inspected Asset List (see Inspection Notes for exceptions)

Asset Category	Equipment (Outdoor Play)
Asset Name	1 bay 2 cradle swings
Asset Sub Type	Type 1 - Traditional (Toddler Seats)
Asset Type	Swing
Manufacturer	Kompan Ltd

Asset Category	Equipment (Outdoor Play)
Asset Name	2 bay swing and birds nest swing
Asset Sub Type	Type 1 - Traditional (Mixed Seats)
Asset Type	Swing
Manufacturer	Kompan Ltd

Asset Category	Facilities
Asset Name	2 litter bins
Asset Sub Type	Litter Bins
Asset Type	Bins
Manufacturer	Kompan Ltd



<b>Asset Category</b>	Facilities
<b>Asset Name</b>	3 picnic tables
<b>Asset Sub Type</b>	Picnic Table
<b>Asset Type</b>	Seating
<b>Manufacturer</b>	Kompan Ltd

<b>Asset Category</b>	Site
<b>Asset Name</b>	Approaches - External Tarmac Path
<b>Asset Sub Type</b>	Other (Specify in Name Field)
<b>Asset Type</b>	Approaches
<b>Manufacturer</b>	

<b>Asset Category</b>	Perimeter
<b>Asset Name</b>	Entrance - Self Closing Gate (MH) x2
<b>Asset Sub Type</b>	Self Closing Gate
<b>Asset Type</b>	Entrance
<b>Manufacturer</b>	

<b>Asset Category</b>	Perimeter
<b>Asset Name</b>	Fence - Chain Link
<b>Asset Sub Type</b>	Chain Link
<b>Asset Type</b>	Fencing
<b>Manufacturer</b>	

<b>Asset Category</b>	Perimeter
<b>Asset Name</b>	Fence - Private Garden
<b>Asset Sub Type</b>	Private Garden
<b>Asset Type</b>	Fencing
<b>Manufacturer</b>	

<b>Asset Category</b>	Perimeter
<b>Asset Name</b>	Fence - Timber Paling
<b>Asset Sub Type</b>	Timber Paling
<b>Asset Type</b>	Fencing
<b>Manufacturer</b>	

<b>Asset Category</b>	Surface
<b>Asset Name</b>	grass
<b>Asset Sub Type</b>	Grass
<b>Asset Type</b>	General Surface
<b>Manufacturer</b>	

<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	Junior spica
<b>Asset Sub Type</b>	Exempt (Diameter less than 500mm)(Pre EN1176:2019)
<b>Asset Type</b>	Carousel
<b>Manufacturer</b>	Kompan Ltd

<b>Asset Category</b>	Perimeter
<b>Asset Name</b>	Maintenance Gate
<b>Asset Sub Type</b>	Maintenance Gate
<b>Asset Type</b>	Entrance
<b>Manufacturer</b>	

<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	Quad tower with climbing net and net bridge multi unit
<b>Asset Sub Type</b>	Multiplay Unit - Toddler
<b>Asset Type</b>	Multiplay
<b>Manufacturer</b>	Kompan Ltd

<b>Asset Category</b>	Facilities
<b>Asset Name</b>	Seat x2
<b>Asset Sub Type</b>	Bench with back rest
<b>Asset Type</b>	Seating
<b>Manufacturer</b>	

<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	See saw
<b>Asset Sub Type</b>	Type 3B - Multi-point - Multi-directional
<b>Asset Type</b>	Rocker
<b>Manufacturer</b>	Kompan Ltd

<b>Asset Category</b>	Site
<b>Asset Name</b>	Site - Sign - Activity Ban
<b>Asset Sub Type</b>	Information
<b>Asset Type</b>	Signage
<b>Manufacturer</b>	

<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	Spinning bowl
<b>Asset Sub Type</b>	Other (Specify in Name Field)
<b>Asset Type</b>	Carousel
<b>Manufacturer</b>	Kompan Ltd

<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	Supernova carousel
<b>Asset Sub Type</b>	Other (Specify in Name Field)
<b>Asset Type</b>	Agility
<b>Manufacturer</b>	Kompan Ltd

<b>Asset Category</b>	Site
<b>Asset Name</b>	The Overall Site
<b>Asset Sub Type</b>	The Overall Site
<b>Asset Type</b>	Site
<b>Manufacturer</b>	



<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	Toddler tower multi unit
<b>Asset Sub Type</b>	Multiplay Unit - Junior
<b>Asset Type</b>	Multiplay
<b>Manufacturer</b>	Kompan Ltd


<b>Asset Category</b>	Equipment (Outdoor Play)
<b>Asset Name</b>	Track ride tower
<b>Asset Sub Type</b>	Rigid
<b>Asset Type</b>	Cableway
<b>Manufacturer</b>	Kompan Ltd

## Findings reported within the Inspection

### 1 bay 2 cradle swings - Findings

Asset	1 bay 2 cradle swings
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15381
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Surface - Wearing
Location	
Risk Level	Very Low


Finding Photos



### 2 bay swing and birds nest swing - Findings

Asset	2 bay swing and birds nest swing
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15383
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Item - Cap(s) missing
Location	
Risk Level	Very Low

Finding Photos



3 picnic tables - Findings

Asset	3 picnic tables
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15379
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Timber - Splintered
Location	
Risk Level	Low

Finding Photos



Asset	3 picnic tables
Cause	Vandalism
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15377
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Item - Graffiti - Present
Location	
Risk Level	Very Low

Finding Photos



Asset	3 picnic tables
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15380
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Entrance - Self Closing Gate (MH) x2 - Findings

Asset	Entrance - Self Closing Gate (MH) x2
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15376
Finding Notes	
Finding Resolved Date	19/07/2024 00:00:00
Finding Status	Closed
Finding Title	Gate - Violent Action
Location	
Risk Level	Low

Finding Photos



Asset	Entrance - Self Closing Gate (MH) x2
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15373
Finding Notes	Gate closing beyond posts - obstructing pathway
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Item - Repair/s - Minor
Location	
Risk Level	Low

Finding Photos



Fence - Timber Paling - Finding

Asset	Fence - Timber Paling
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15374
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Timber - Smashed
Location	
Risk Level	Very Low

Finding Photos



Quad tower with climbing net and net bridge multi unit - Findings

Asset	Quad tower with climbing net and net bridge multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15390
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Quad tower with climbing net and net bridge multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15389
Finding Notes	
Finding Resolved Date	27/08/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Low

Finding Photos



Asset	Quad tower with climbing net and net bridge multi unit
Cause	Vandalism
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15384
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Item - Graffiti - Present
Location	
Risk Level	Very Low

Finding Photos



Asset	Quad tower with climbing net and net bridge multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15387
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Quad tower with climbing net and net bridge multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15388
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Quad tower with climbing net and net bridge multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15385
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos





Asset	Quad tower with climbing net and net bridge multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15386
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Seat x2 - Finding

Asset	Seat x2
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15378
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Item - Broken
Location	
Risk Level	Low

Finding Photos



Supernova carousel - Finding

Asset	Supernova carousel
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15382
Finding Notes	Seal missing from track
Finding Resolved Date	
Finding Status	Open
Finding Title	Item - Parts Missing
Location	
Risk Level	Low

Finding Photos



The Overall Site - Finding

Asset	The Overall Site
Cause	Routine
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15375
Finding Notes	
Finding Resolved Date	09/09/2024 00:00:00
Finding Status	Closed
Finding Title	Site needs spraying for weeds
Location	
Risk Level	Very Low

Finding Photos



Toddler tower multi unit - Findings

Asset	Toddler tower multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15396
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Toddler tower multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15398
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Toddler tower multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15397
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Toddler tower multi unit
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15395
Finding Notes	
Finding Resolved Date	
Finding Status	Open
Finding Title	Surface - Wearing
Location	
Risk Level	Very Low

Finding Photos



Track ride tower - Findings

Asset	Track ride tower
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15391
Finding Notes	Drag chain
Finding Resolved Date	
Finding Status	Open
Finding Title	Item - Parts Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Track ride tower
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15393
Finding Notes	
Finding Resolved Date	08/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Track ride tower
Cause	Wear and Tear
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15394
Finding Notes	
Finding Resolved Date	15/07/2024 00:00:00
Finding Status	Closed
Finding Title	Fixtures - Loose or Missing
Location	
Risk Level	Very Low

Finding Photos



Asset	Track ride tower
Cause	Anti Social Behaviour
Finding Creation Date	01/07/2024 10:13:00
Finding Group	Maintenance
Finding ID	F15392
Finding Notes	
Finding Resolved Date	19/07/2024 00:00:00
Finding Status	Closed
Finding Title	Item - Rope Attached
Location	
Risk Level	Medium

Finding Photos

